

Date Placed in
Operation: Jan 1983

Drainage Area in
Sq. Mi.: 353

TAYLORSVILLE LAKE

FREQUENCY OF EXCEEDENCE*	ELEVATION M.S.L.	FACILITIES
	623	TOP OF DAM
	592	FLOOD POOL - SPILLWAY CREST
5 Yr.	565	Van Buren - Boat launch difficult, limited parking
	564	Settlers Trace (Taylorsville Lake Dock) - Electric service has to be disconnected
	563	Chowning Lane - boat launch difficult, limited parking
	562	Settlers Trace - Inaccessible by roadway, causeway inundated
	558	Settlers Trace - Boat launch difficult, limited parking
	552	Bulkheads stored
	547	SUMMER POOL LEVEL
	545	WINTER POOL LEVEL
	543	Settlers Trace (Taylorsville Lake Dock) - Potable water line becomes exposed and susceptible to freezing. Walkway becomes unusable as constructed.
	538.5	Poosum Ridge, Van Buren - Lower end of concrete launch ramp becomes one lane.
	538	Chowning Lane - Lower end of concrete launch ramp.
	537.6	Ashes Creek - Lower end of concrete launch ramp.
	519	Settlers Trace - Lower end of concrete launch ramp.

TAYLORSVILLE LAKE (cont.)

Date	Record Pools		Operating Levels		
	Elevation	Pool	Elevation M.S.L.	Area Acres	Length Miles
Mar '97	586.5				
Feb '89	580.4				
Jan '91	579.8	Winter	545	2930	18.2
May '95	568.7	Summer	547	3050	18.5
May '83	565.3	Flood	592	6350	22.8
May '84	563.5				

***Frequency of exceedence based on simulated operation for the years 1939-1980.**